## INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: <u>Amos Alexander (Beers) Farm</u>	Survey Number: <u>CE-300</u>		
Project: <u>Restoration of Springhouse</u>	Agency: <u>DNR/non profit organ.</u>		
Site visit by MHT Staff: X no yes Name	Date		
Eligibility recommended $X$ Eligibility <b>not</b> reco	mmended		
Criteria:AB _X_CD Considerations:A	_BCDEFGNone		
Justification for decision: (Use continuation sheet if	necessary and attach map)		
The Amos Alexander Farm is an early to mid-nineteenth centand a half story stone house with subsequent nineteenth centamokehouse, food storage building and springhouse. Located anagament Area, the farm complex was surveyed in 1977 architectural significance and method of construction, setting, location, and materials. Recent investigation eligibility of the property. The stone springhouse has succollapse of the shingle roof, mortar failure and wood roopenings remain. The overall integrity of the property is the springhouse demonstrates the most deterioration. It was the Secretary of the Interior's Standards.	entury additions, c. 1826 bank barn, ed in the Fair Hill Natural Resource and determined eligible for its. The property retains its design, as by James Wollon reiterated the suffered deterioration including the at. The original door and louvered is sufficient for eligibility while		
Documentation on the property/distr	ict is presented in:		
Preparedby: _JohnHnedak_			
L. Bowlin 11 Reviewer, Office of Preservation Services	-29-93		
	Date		
NR program concurrence: yes no not applic	,		
Reviewer, NR program	Date		
• -	· · · · · · · · · · · · · · · · · · ·		

Survey	No.	CE-300	

## MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I.	Geographic Region:			
<u>X</u>	Eastern Shore Western Shore	<pre>(all Eastern Shore counties, and Cecil) (Anne Arundel, Calvert, Charles,   Prince George's and St. Mary's) (Baltimore City, Baltimore, Carroll,</pre>		
	Piedmont			
	Western Maryland	Frederick, Harford, Howard, Montgomery) (Allegany, Garrett and Washington)		
II.	Chronological/Developmental Periods:			
XX	Paleo-Indian Early Archaic Middle Archaic Late Archaic Early Woodland Middle Woodland Late Woodland/Archaic Contact and Settlement Rural Agrarian Intensification Agricultural-Industrial Transi Industrial/Urban Dominance Modern Period Unknown Period ( prehisto	tion A.D. 1815-1870 A.D. 1870-1930 A.D. 1930-Present		
III.	Prehistoric Period Themes:	IV. Historic Period Themes:		
	Subsistence Settlement  Political Demographic Religion Technology Environmental Adaptation	X Agriculture X Architecture, Landscape Architecture, and Community Planning Economic (Commercial and Industrial) Government/Law Military Religion Social/Educational/Cultural Transportation		
V. Re	esource Type:			
	Category: <u>Buildings</u>			
	Historic Environment: <u>rural</u>			
	Historic Function(s) and Use(s): <u>domestic, agricultural</u>			
	Known Design Source:			

Inventory Numbers: CE-300, CE-300-B, CE-300-C

Beers Complex Cecil County, MD C. Mazurek June 1998 Section 7.1

## Addendum


The Beers Complex is located in Cecil County, within the Fair Hill N.R.M.A., and to the east of the Big Elk Creek Covered Bridge. It is situated right on the Management Area dirt access road, on a hillside overlooking the Big Elk Creek.

The Beers house (CE-300) is a rental property by the Department of Natural Resources and is in excellent condition. Since the last survey was completed in 1978-1979 the exterior structure has remained the same, with the exception of the front porch posts. The old wood posts, the bottom half a squared shape and the upper half a rounded shape with a doric capital, have been replaced with completely squared wood posts with straight brackets at the top.

The Beers Smokehouse (CE-300-B) has lost it's front batten door with tapered iron strap hinges, however it may still be located on the property somewhere. The gable roof is intact and keeps the rain out of the understructure. Some of the vegetation around the Smokehouse has been allowed to grow too close to the foundation and stone retaining wall, but it has not yet led to deterioration.

The Beers Stable and Hayloft/Garage (CE-300-C) are kept in good condition, with no apparent alterations to the exterior of the structures. As with the Smokehouse, vegetation near the Hayloft/Garage has been allowed to grow too close to the foundation.

A wood frame storage barn with sheet metal siding has been constructed just to the east of the Beers House. The rear facade (south) opens up to a wood fenced-in field. This structure is not historic.





14.a

CE-300
ROOPS BARN, FAIR HILL N.R.M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

N.W. ELEVATION



CE-300 BEERS HOUSE, FAIR HILL N.R.M.A. CECIL COUNTY, MD C. MAZUREK DEPT. OF NATURAL RESOURCES N.E. ELEVATION



CE-300 BEERS BARN, FAIR HILL N.R.M.A. CECIL COUNTY, MD C. MAZUREK

DEPT. OF NATURAL RESOURCES EAST ELEVATION



CE-300 BEERS COMPOUND, BARN, FAIRHILL N.R.M.A. CÉCIL COUNTY, MD C. MAZUREK DEPT. OF NATURAL RESOURCES N.E. ELEVATION



14.C CE-300 BEERS COMPOUND HAY LOFT, FAIR HILL NIRMA. CELIL COUNTY, MD C. MAZUREK 12/97 DEPT. OF NATURAL RESOURCES S.W. ELEVATION



14.d (F-300 BEERS COMPOUND SMOKEHOUSE, FAIR HILL N.R.M.A. CECIL COUNTY, MD C. MAZUREK 12/97 DEPT. OF NATURAL RESOURCES S.E. ELEVATION



14.e CE-300 Beeps Compound SpringHouse FAIR HILL N.R.MA CECIL COUNTY, MD C. MAZUREK 12/97 DEPT. OF NATURAL RESOURCES FACING EAST



CECIL COUNTY, MD; FAIR HILL N.R.M.A.

BARN

C. MAZUREK

DEPT. OF NATURAL RESOURCES

NAPTH EAST ELEVATION

## BEERS FARM - RECOMMENDATIONS

DNR-10 House CE-300 DNR-11 Barn CE-300-A

DNR-12 Smokehouse CE-300-B

DNR-13 Hayloft CE-300-C

At least the 1826 Barn, if not this entire complex, is eligible for the National Register, probably in company with its near twin across Big Elk Creek, the Finley Barn (DNR-4/CE-301-A). The complex is occupied and appears to be prosperous and in good repair. Routine maintenance and upkeep should be carried out with an eye toward a return to an original appearance.

For example, the replacement of a composition roof should be done in shakes or standing-seam metal. There appears to be no serious structural problems. The house raises some interesting questions of date, and a detailed physical examination is warranted because of them. This may be arranged with the Maryland Historical Trust. In anticipation of future needs for major work, it should be done soon. Any changes in the property should be carried out only after consultation with the Maryland Historical Trust.

NO. OF STORIES

1. STATE Maryland HISTORIC AMERICAN BUILDINGS SURVEY County Cecil INVENTORY CE-300 VICINITY Fair Hill Bee⊯s House 2. NAME STREET NO. Target DATE OR PERIOD 19th Cent. ORIGINAL OWNER "Colomid" STYLE dwelling ORIGINAL USE ARCHITECT PRESENT OWNER BUILDER PRESENT USE dwelling WALL CONSTRUCTION STONE 3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC NO

The Beens House, on the William DuPont Estate at Fair Hill, Cecil County, is a small early 19th. Century stone structure with subsequent additions. Out buildings and barns surround the house, all built on the side of a small hill overlooking the meadow and Big Elk Creek.

The south port of the stone structure is a one and one half story, three bay house having a chimney in each end. It appears to be the earliest portion of the house, though the half on the north must have followed soon after. The latter is built "down hill" from the former and is two full stories tall, even though the roof line is continuous. A frame wing and porches probably date from Mr. DuPont's ownership. Although the house is presently unoccupied, it is in good physical condition.

North of the house is a stone bank barn with a plaque bearing the date 1826. It has three sides of stone and a "bridge" from the road into the second story. There are several other sheds surrounding the barn.

Courtesy of William Shelton, Mgr.

5. PHYSICAL CONDITION OF STRUCTURE Endangered NO Interior Exterior good

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

3- PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

Visited and photographed by Michael Bourne, 11/12/71

9. NAME, ADDRESS AND TITLE OF RECORDER

DATE OF RECORD

NO. OF STORIES

COUNTY Maryland HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY CE-300 Cecil TOWN VICINITY 2. NAME STREET NO. Beens House DATE OR PERIOD 19th Century ORIGINAL OWNER " Colonial" STYLE ORIGINAL USE dwelling ARCHITECT PRESENT OWNER BUILOER PRESENT USE dwelling 3. FOR LIBRARY OF CONGRESS USE WALL CONSTRUCTION Stone

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC N

The Beens House, on the William DuPont Estate at Fair Hill, Cecil County, is a small early 19th. Century stone structure with subsequent additions. Out buildings and barns surround the house, all built on the side of a small hill overlooking the meadow and Big Elk Creek.

The south port of the stone structure is a one and one half story, three bay house having a chimney in each end. It appears to be the earliest portion of the house, though the half on the north must have followed soon after. The latter is built "down hill" from the former and is two full stories tall, even though the roof line is continuous. A frame wing and porches probably date from Mr. DuPont's ownership. Although the house is presently unoccupied, it is in good physical condition.

North of the house is a stone bank barn with a plaque bearing the date 1826. It has three sides of stone and a "bridge" from the road into the second story. There are several other sheds surrounding the barn.

Courtesy of William Shelton, Mgr.

5. PHYSICAL CONDITION OF STRUCTURE Endangered NO Interior Exterior good

6. LOCATION MAP (Plan Optional)


7. PHOTOGRAPH

3. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, AODRESS AND TITLE OF RECORDER

Visited and photographed by Michael Bourne, 11/12/71

DATE OF RECORD



The Beers House, on ten w DiPart Estate at

Fair Hill, Ceal Cowing is a small early 19th Century

Stone structure with subsequent additions.

Outhwildwip and basms surround the house,
all built on the side; a small hill

are bouth part; he stone structure

to a 1's stony, 3 bay house having himing in

lack end. It appears to be due earliest

portion, the base, though he had on

the North must have followed soon ofter.

the latter is built 'down-hill' from the form

this 2 full stone tall, event though the


nog line is continuous. A grame wing to


porches probably date from Mr. DePort's sumstaship. Although the house to presently unoccupied, it is in good physical condition.

Thorth De house to a stone boanh boarn who as plague bearing the date 1826. It has 3 side o of one and a bridge from the road into the 2nd story. There are sereal other sheds and born sworpending the boarn.

11/15/11

Visited + photographed by M900 11/12/71 Countary of William Shelton, Mgr.







Beers House BigEIK TAIR HILL, MD.
1976 CE-300

Beers House FAIR HILL, MA

6 WL



Beers House FAIR HILL, MD.

GWV

1976 CE-300



Beers Barn and House FAIR HILL, MD. CE-300




MAY

Outbuilding Beers FAIR HILL, MP.



Outbuilding Beers FAIR HIW, MD. 1976 CE-300



Interior Beers Outbuilding FAIR H.L. 1976 CE-300 MD.



LOGJOISTS Beers FAIR HILL, MD.
1976 CE-300



Beers House Near Fair Hill NOrtheast Elevation MOB/1971 NEG - MD. Hist. Trust

4

CE - 300